



## PACKING LIST FOR C500

**Box 1 - C500 Sensor Unit** **Wt: 3 lbs. Dim: 12"x 13"x 5"**

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
1 C500	Main Sensor Unit	1
2 000-114-805	Fuse FGMB 1A	2
3 000-802-080	Tapping Screw M4 x 16	2
4 000-125-237	Cable Assembly 10M w/ Plugs	1
5 000-145-612	Cable Assembly 2M w/ Plugs	1
6 OME-725-50Z	Operator's Manual C500/PG500	1

<i>For Internal Use Only</i>	
Serial No. _____	
Checked By: _____	
Tech	_____
Date	_____
C500	
<u>Yes</u>	<u>Remarks</u>
	sub SP64-01301
	sub CP64-02101